


PINOUTS OF CONNECTORS



+12VDC

COM

COM

+5VDC

+5VDC COM COM

+12VDC

Main Power Connector

+12V = yellow +5VSB = brown -5V = white+5V = red PS_ON# = gray -12V = blue +3.3V = purplePWR_OK = orange COM = black

